Intel® Chipset Device Software 9.2.3.1020 For JakeTown and Patsburg

Release Notes

August 9, 2011

Microsoft Windows* 2000
Microsoft Windows* XP
Microsoft Windows* XP Professional x64 Edition
Microsoft Windows* Server 2003
Microsoft Windows* Server 2003 x64 Edition
Microsoft Windows* Vista
Microsoft Windows* Vista x64 Edition
Microsoft Windows* Server 2008
Microsoft Windows* Server 2008 x64 Edition
Microsoft Windows 7
Microsoft Windows 7 x64 Edition
Microsoft Windows Server 2008 R2 X64

described as "known issues" which may cause the product to deviate from expected performance. Current characterized known issues are documented in this update.

Revision History

Date	Driver Revision	Draft/Changes
August 2011	9.2.3.1020	See below

Intel® Chipset Device Software Support

The Intel® Chipset Device Software contains support for the following Intel Chipsets:

- Patsburg and Jaketown
- Intel® 5 Series Chipsets
- Intel® 3400 Series Chipsets
- Intel® 4 Series Chipsets
- Intel® 3 Series Chipsets
- Intel® 900 Series Chipsets
- Intel® 800 Series Chipsets
- Intel® Server/Workstation Chipsets

Supported Operating Systems

The Intel® Chipset Device Software is validated on the following Microsoft operating systems.

- Microsoft Windows* 2000
- Microsoft Windows XP
- Microsoft Windows XP Professional x64 Edition
- Microsoft Windows Server* 2003
- Microsoft Windows Server* 2003 x64 Edition
- Microsoft Windows Vista* RTM and SP's
- Microsoft Windows Server* 2008
- Microsoft Windows Server* 2008 x64 Edition
- Microsoft Windows 7
- Microsoft Windows 7 x64

New Features, Fixes & Changes

Features Added WHQL - 9.2.3.1020 – 08/09/2011
Description
WHQLed

Features Added - 9.2.3.1017 – 06/17/2011
Description
1. Updated Name String on 1D3E 2. Added HECI INF

Features Added WHQL- 9.2.3.1016 – 04/22/2011
Description
WHQLed to 1.6

Features Added in Beta 9.2.3.1015 – 04/07/2011
Description
1. Jaketown name changes 2. Updated Installer with Klockwork scan fixes 1.1.42
3. Updated Official Branding For Patsburg

4. Moved to Installer Label 1.1.36
    a. Updated extractdriver function
    b. Creates MUP.xml (packageversion not correct)

Features Added in Alpha 9.2.3.1010 – 02/28/2011
Description
Added support for Waimea Bay platform

Features Added in Alpha 9.2.3.1010 – 01/14/2011	
ID	**Description**
1	Removed Commented SMB from PatCore
2	Fixed spelling of Controller in AHCI and IDE inf files

Features Added in Alpha 9.2.3.1009	
1	Added 1D41 LPC device

Features Added in Alpha 9.2.3.1008	
1	Changed ® to (R)
2	3C00 changed to No_Drv for the "A" stepping in order for a BOSD not to occur
3	Removed 3C60 and 3C61
4	Added 1D76 and 1D77
5	Added Audio INF (1D20)

Features Added in Alpha 9.2.3.1004	
1	Removed commented out Devices from JakeTown.Inf
2	Changed Installer Version to 1.1.32 (Fixes –overall switch and 2nd install of filtered INF files)

Features Added in Alpha 9.2.3.1003	
ID	**Description**
1	JakeTown.inf: commented out PCI devices 3C00-3C0F
2	Changed 3C88 to 3C90
3	Added 3C44 QPI Link
	Added 3CE4 R2 PCIe
Features Added in Alpha 9.2.2.1002	
	Commented out 3C02 from jaketown.inf
Features Added in Alpha 9.2.2.1001	
	Added JakeTown.inf Updated all Patsburg related INF

Software Sightings and/or Known Issues

ID	Information
1	After version 9.2.3.1004 B0 must be used (jaketown B0 should be used with Patsburg B0)